



Spareparts



SLIJPMOLEN PSM 300 D
TOURET A MEULER PSM 300 D

CE

Bestelnr./N° de cde. 51117

PSM 300 D

1. Screw
2. Spring Washer
3. Left Support
4. Ball Bearing
5. Centrifugal Switch #
6. Screw
7. Stator Housing
8. Stator
9. Rotor Shaft*

10. Fan
11. Right Support
12. Ext. Washer
13. Copper Set
14. Int. Washer
15. Screw
16. Grommet Rubber
17. Running Capacitor
18. Clamp
19. Screw

20. Grinding Base
21. Screw
22. Cable Strainer
23. Fixing Plate
24. Power Cord
25. Washer
26. Screw
27. Base Plate
28. Pad
29. Screw

30. Screw
31. NVR
32. Overload Protector*
34. Spring Washer*
35. Hex. Nut*
36. Screw
37. Screw
38. Spring Washer
39. Disc Washer

40. Grinding Wheel
41. Sleeve
42. Hex. Nut
43. Eyeshield Set
44. Right Int. Cover A
45. Right Wheel Cover A
46. Screw
47. Left Int. Cover A
48. Left Wheel Cover A
49. Toolrest

50. Hex. Bolt
51. Washer
52. Right Int. Cover B
53. Right Wheel Cover B
54. Left Int. Cover B
55. Left Wheel Cover B
56. Wire Brush
57. MOP/Buffer
58. Set Screw
59. Balance Block

60. Washer
61. Balancing Flange
62. Rotor Shaft*1
63. Rotor Shaft*2
64. Dust Collector
65. Hex. Bolt
66. Washer
67. Chip Outlet
68. Screw
69. Spring Washer

70. Starting Capacitor *
71. Clamp *
72. Hex. Nut *
73. Wiring Board

for GR 10, CN10 only
(Single phase)

* for GR type

* for GR10, CN10 and
PR 10 only

44+45+47+48 for GR type
47+48+52+53 for CN type
52+53+54+55 for PR type

*1 for CN type
*2 for PR type

*for GR 10, CN10 only
(Single phase)

